#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-020305 Address: 333 Burma Road **Date Inspected:** 16-Jan-2011

City: Oakland, CA 94607

**Project Name:** SAS Superstructure OSM Arrival Time: 1900 **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** See below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** OBG

### **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for observations relative to the work being performed.

#### Bay 14

This QA inspector performed MT of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report, for document number 08197, on this date. The member was identified as OBG-13AE. The weld designations reviewed are as follows:

SEG3007M-201, 206, 211, 216, 221, 226 SEG3007P-234, 239, 244, 249, 254, 259 SA3012A-109 ~ 119, 122, 143, 144, 147, 148, 151, 152, 155, 156, 159, 160, 163, 164,178

This QA inspector performed Magnetic Particle Inspection on Segment 13AE as per NWIT 08197 Item 1. This QA inspector identified several locations where Visual and MT indications have been noted, due to ZPMC not having labor personnel to grind these locations on this date to defer from relevant and non-relevant indications, these areas have been turned over to day shift personnel to have ZPMC grind these areas that have been clearly marked.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)





# **Summary of Conversations:**

No significant conversations

# **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Leavitt, Kelly	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer